




3. Material Characteristics

Property	Requirement
Transmittance	88±2 %
Surface hardness	7H
Operating temperature	-30 ~ 80 °C
Storage temperature	-40 ~ 85 °C
Operating Humidity	20 ~ 90% RH (Max.50 °C)
Storage Humidity	20 ~ 90% RH (Max.50 °C)

4.Tolerance no specified : ± 0.50mm

5.Marked the size of the "Q" key measurement size

6.The head of FPC can not pulled



7.Component area of stiffener board on FPC can not be bent.

